



October 21, 2016

Mr. Peter J. Kampa

Lake Don Pedro CSD
9751 Merced Falls Road
La Grange, CA. 95329

Quote # 101716-1QR

FAX: 209-852-2268

Email: pkampa@kampacs.com

Dear Peter:

ERS is pleased to submit its proposal for our TurnKey Repair Service on your 1 each 8' x 30' 2 cell Horizontal Pressure Vessel. The second filter will be evaluated after the first filter is up and running.

Our service includes the following:

ERS to provide:

1. Repair bulkhead at Influent and Effluent manifolds
2. Weld Stiffener to bulk head
3. Replace 84ea 1 1/4" Half coupling's to existing effluent manifold
4. Clean Surface Wash Nozzles & Replace rubber seals
5. Supply and install new surface wash manifold
6. Replace Elliptical man way covers 4ea
7. Supply and Install 1ea new 8" isolation valve on outside of building
8. Supply and Install 2ea new 6" isolation valve on outside of building
9. Supply and Install 1ea new 3" Isolation valve on outside of building
10. Supply and install 2 new 3/4" Air Relief Valves
11. Supply and install drain screen at end of filter
12. Sand Blast Interior of filter vessel to SSPC 10 and coat with 1 coat of SW Sherplate PW to a DFT of 40 – 50 mil
13. Prep, Spot Prime and coat outside of vessel with 1 coat of SW Sher-cryl High Performance Acrylic (White)

PRICING: 1 Filter Only

\$101,458.64

Includes Prevailing Wage---ERS DIR # 1000003275

Quote Valid for 45 days

Price includes all applicable sales tax.

Please feel free to call me should you need further information or any clarification. My cell phone is 510-552-5301; office is 510-770-0202.

Sincerely,

Accepted By: _____ Date: _____

Rick D. Langlois
Vice President Sales